Toronto District School Board

George Syme Community School Update

PROGRESS OF CONSTRUCTION WORK

- 1. Windows installation completed.
- Roofing completed except for the small south canopy to be done during the weekend.
- 3. Millwork installation in progress.

<u>UPCOMING WORK</u>

- 1. Roof Top Unit.
- 2. Elevator.
- 3. Continue Brick Veneer
- 4. Continue mechanical and electrical
- 5. Continue Asphalt and outdoor work
- 6. Metal Siding installation.

COMMUNITY UPDATE:

There will be earthwork/outdoor work that may cause vibrations, so TDSB has hired a third-party consultant to monitor and manage the vibrations and ensure that all the readings are in accordance with the city's regulations.

CONSTRUCTION PROGRESS PHOTOS:

West Facade





George Syme Community School Update

Southeast Corner



• One of the Classroom

